## RECOGNIZED BYTE CLASS ASSOCIATION



The following amendments to the Class Rules has been approved to be effective  $07^{\text{th}}$  August 2009.

## **Current Rule:**

None

# **New Rule:**

12(q)

The traveller block may be attached to the traveller bar or its attachments by any adjustable rope bridle in which case a preventive line may be attached between the block and the car. Holes may be drilled in the traveller bar for this purpose. A second traveller car as supplied by the manufacturer may be attached to the traveller bar in which case the bridle shall be attached to both cars and the traveller control lines may be used to control both cars independently.

## **Current Rule:**

None

#### **New Rule:**

12(r)

A maximum of two rope righting lines may be attached to any existing fittings in the cockpit. Alternatively they may be attached under the gunwale by any clips or eyes in which case the fastener heads shall be covered by any sealant and not protrude the deck surface; a shock cord retractor may be rigged to the system.